https://crc.army.mil

A Soldier was injured in a motorcycle accident Apr. 12 at approximately 0930 local near Pierce, Wash. The Soldier was commuting to work on his motorcycle and waiting at a controlled intersection to make a left-hand turn when he was rear-ended by a car and thrown from his motorcycle. He was wearing the required PPE and had attended an Army-approved Motorcycle Safety Foundation Course.

COST: 1 Soldier Injured

A Soldier was injured in a motorcycle accident Apr. 12 at approximately 1915 near Pierce, Wash. The Soldier was operating his motorcycle when he attempted to turn onto an exit and lost control of his motorcycle causing him to crash to the pavement. The weather conditions at the time

of the accident were dark with rain, sleet and hail resulting in wet and hazardous road conditions. He was wearing the required PPE and had attended an Army-approved Motorcycle Safety Foundation Course.

COST: 1 Soldier Injured

A Soldier was killed in a motorcycle accident Apr. 17 at 1430 local in Coxton, Ky. The Soldier was operating a 2006 Suzuki Hayabusa GSX1300R motorcycle at a high rate of speed when he lost control of the motorcycle while negotiating a curve. The motorcycle left the roadway and hit a rock embankment and then came to a stop by a tree. The Soldier had taken an Army-approved Motorcycle Safety Foundation Course and knew the PPE requirement but chose not to wear a

helmet. The Soldier had received a motorcycle safety face-to-face counseling with his supervisor in accordance with FORSCOM's "Privately-Owned Vehicle/ Motorcycle Safety Memorandum." He was pronounced dead at the scene.

COST: 1 Soldier Killed

A Soldier was killed in a Range Live Fire accident Apr. 18. The Soldier was the first in line on a four-man team conducting room clearing procedures during a live-fire exercise when he was shot. PPE and night vision devices were being used. The Soldier was pronounced dead at a local medical facility.

COST: 1 Soldier Killed

A Soldier was killed in a vehicle accident Apr. 18 at approximately 2254 local in Clarksville, Tenn. The Soldier was the driver of a 2002 Jeep Cherokee when he lost control of the vehicle. The vehicle left the roadway, struck a guard rail and traveled along it for a short distance before rolling over into a grassy area adjacent to the roadway. The Soldier was not wearing a seat belt and was ejected from the vehicle. He was pronounced dead at the scene. A small child and two adults that were passengers in the vehicle are in critical condition at a local medical center. Only one adult was wearing a seat belt. The child was not in an approved child seat but buckled into an adult seat belt.

COST: 1 Soldier Killed

Preliminary LOSS IREPORTS for the week of 12-18 APR 07



U.S. SOLDIERS DIED IN ACCIDENTS

2 Soldiers Injured



ARMY STRONG



